

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 87504-2088

| | |
|------------------------------|--|
| WELL API NO. 30-025-34110 | |
| 5. Indicate Type of Lease | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|--|---|
| 1 Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. Lease Name or Unit Agreement Name Caprock Maljamar Unit |
| 2. Name of Operator The Wiser Oil Company | | 8. Well No. 282 |
| 3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241 | | 9. Pool name or Wildcat Maljamar Grayburg San Andres |
| 4. Well Location Unit Letter <u>N</u> : <u>1310</u> Feet From The <u>South</u> Line and <u>1892</u> Feet From The <u>West</u> Line Section <u>28</u> Township <u>17S</u> Range <u>33E</u> NMPM <u>Lea</u> County | | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4088' | | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO | | SUBSEQUENT REPORT OF: | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| OTHER: <input type="checkbox"/> | | OTHER: <u>Perforate, Acidize & Frac</u> <input checked="" type="checkbox"/> | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09/25/97 Halliburton perforated San Andres Upper Jackson f/4531'-34', 37'-56' & 64'-77' w/1 SPF (38 holes). RIH w/5-1/2" Baker pkr. on 2-7/8" tbg. to 4410'. Tested tbg. to 5,000#.

09/26/97 Set pkr. @ 4470'. HES acidized San Andres Upper Jackson perfs. 4531'-4577' w/5500 gals. 15% NE-FE acid & 74 ball sealers. Formation broke @ 2497#. ATP 3000# @ 3.8 bpm. MTP 3380# @ 4.7 bpm. Good ball action. Did not ball out. ISIP 2648#. 5 min. 1685#. 10 min. 1188#. 15 min. 909#. POH w/tbg. & pkr.

09/29/97 Halliburton perforated Grayburg f/4312', 13' & 18'-29' w/1 SPF (14 holes). RIH w/5-1/2" Baker RBP & pkr. on 2-7/8" tbg. Set RBP @ 4400'. Set pkr. @ 4380'. Tested RBP to 3500#. HES acidized Grayburg perfs. 4312'-4329' w/2100 gals. 15% NE-FE acid & 28 ball sealers. Formation broke @ 3011#. ATP 3000# @ 3.5 bpm. MTP 3660# @ 4.6 bpm. Balled out w/4750#. ISIP 2887#. 5 min. 2577#. 10 min. 2236#. 15 min. 2048#.

09/30/97 Unset pkr. & POH. LD tbg. & pkr. ND BOP. Installed frac valve.

10/01/97 HES frac'd Grayburg perfs. 4312'-4329' w/9500 gals. gelled water, 15,500 gals. 20# Delta Frac & 36,000# 16/30 brown sand. ATP 3800# @ 20 bpm. MTP 4435# @ 21.2 bpm. Screened out @ 5093# w/4.7# sand @ perfs. ISIP 4727#. Approx. 13,000# sand in formation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Completion Department Date January 9, 1998
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797
(This space for State Use)

ORIGINAL SIGNED BY

APPROVED BY GARY WINK TITLE FIELD REP. II DATE MAR 02 1998

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 87504-2088

| |
|---|
| WELL API NO. 30-025-34110 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name Caprock Maljamar Unit |
| 8. Well No. 282 |
| 9. Pool name or Wildcat Maljamar Grayburg San Andres |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4088' |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1 Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | |
| 2. Name of Operator The Wiser Oil Company | |
| 3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241 | |
| 4. Well Location Unit Letter N : 1310 Feet From The South Line and 1892 Feet From The West Line Section 28 Township 17S Range 33E NMPM Lea County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4088' | |

| | |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: Cleaned out sand <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/02/97 NU BOP & enviro-vat. RIH w/notched collar on 2-7/8" tbg. to 2077'. Cleaned out sand f/2077'-2577'. Cleaned out sand f/3055'-3355'.

10/03/97 Cleaned out sand f/3355'-4269'. Cleaned out sand to 4400'. Pulled to 4200'.

10/06/97 RIH w/tbg. Tagged @ 4310'. Had 90' fill. Pulled to 4200'.

10/07/97 Cleaned out sand f/4310'-4400'. POH w/tbg. RIH w/retrieving head & tbg. Released RBP & POH. RIH w/PS, SN & 2-7/8" tbg. to 3900'.

10/08/97 RIH w/2-7/8" tbg. ND BOP. Set TAC w/10,000# tension. Tbg. @ 4613'. SN @ 4584'. TAC @ 4239'. RIH w/2-1/2" x 2" x 20' RHTC pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Completion Department Date January 9, 1998

TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____