

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34944
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	195
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3973'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>A</u> : <u>669</u> Feet From The <u>NORTH</u> Line and <u>10</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3973'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-30-00/4-17-00: MIRU SU. TIH W/TBG. TAG FC @ 4818.43'. RUN CASED HOLE GR-CCL LOG FR 4817-3500'. PERF 4689-4698,4676-4686, 4654-4674,4642-4652,4627-4635,4616-4624,4605-4608,4601-4602,4571-4588,4556-4560,4546-4552,4509-4538,4500-4504,4491-4496,4479-4483,4456-4465,4449-4455, MIRU PUMP TRUCK, PUMP 12 BBLs 2% KCL. PERF 4423-4431,4415-4421,4399-4413,4393-4394,4385-4387,4379-4383, 4371-4376,4352-4360, PUMP BBLs 2% KCL. CAUGHT PSI. TIH W/TP, PKR & 2 7/8" TBG. EOT @ 4328. PKR @ 4258'. SPOT 400 GALS 15% HCL ACR PERFS. ACIDIZE PERFS FROM 4352-4698 W/18,000 GALS 15% HCL. TIH W/BIT. TAG FILL @ 4557'. MIRU REV UNIT. WASH ^ C/O FR 4557-4810. PBTD @ 4810. TIH W/PROD TEST EQPT. 130 JTS 2 7/8" TBG @ 4136.29, DRAIN PLUG @ 4136.84, CHECK VALVE @ 4201.64, SUB @ 4272.2, X-OVER @ 4272.85', HU FLOWLINE & ELECTRICAL. PUT ON TEST @ 9:40 AM 4-04-00. TIH W/PROD TBG ASSEMBLY FOR ROD PUMPED WELL 4-10-00.
2.50"x1.50"HHBC-24-4 INSERT PUMP NO GAS ANCHOR.
ON 24 HR OPT. 4-16-00. PUMPED 71 BO, 5 BLW, & 0 MCF. PUMPED OFF ON 144" LOS, 7 SPM.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 7/13/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE