

COPY TO O. C. C.  
UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
SUBMIT IN TRIPPLICATE\*  
(Other instructions on  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC 063345

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

TR 4

8. FARM OR LEASE NAME

Pearsall Queen Sand Unit

9. WELL NO.

1 B

10. FIELD AND POOL, OR WILDCAT

Pearsall Queen

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Section 4, T 18S, R 32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL ☐ GAS ☐  
WELL ☒ WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C.E. LaRue & B.N. Muncy, Jr.

3. ADDRESS OF OPERATOR

P. O. Box 196 Aretsia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

600 FNL & 600 FWL; Section 4, T 18S, R 32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3878 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FEATHER TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☐

(Other) plumbing for casing leak survey ☒  
(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Installed necessary plumbing for casing leak survey.

Two inch was plumbed to surface with braiding head connection consisting of a  
2000# valve. At or above the surface, a one inch swage was connected to a one  
inch 2000# valve.

Inspected and approved by Ms. W. Kelly; March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Overseer

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

APR 24 1979

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

RECEIVED

1977-1978

1977

1978

1977-1978  
U.S. DEPARTMENT OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION  
WASHINGTON, D.C. 20535