

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
C.E. LARUE
3. ADDRESS OF OPERATOR
PO BOX 1370 ARTESIA, NM 88211-1370
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL AND 660' FEL SEC 5, T18S, R32E
14. PERMIT NO.
30-025-00840
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
Hobbs, NM 88241

5. LEASE DESIGNATION AND SERIAL NO.
8910086380 LC 029403-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
PEARSALL QUEEN SAND UNIT
8. FARM OR LEASE NAME
9. WELL NO.
TRACT 1 WELL 1
10. FIELD AND POOL, OR WILDCAT
PEARSALL QUEEN
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
SECTION 5, T18S, R32E
12. COUNTY OR PARISH
LEA
13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☒
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

OUR RECORDS INDICATE THAT 7" CASING WAS SET AT 3650' W/100 SACKS CEMENT. TOP OF CEMENT AT 2851'. WELL PRODUCED OPEN HOLE FROM 3650' - 3755'. 7" CASING IS COLLAPSED AT @ 2800'. 3 ATTEMPTS HAVE BEEN MADE TO CLEAN OUT BACK TO BOTTOM, BUT INSTEAD WE GO OUTSIDE THE CASING.

PROPOSE TO MAKE ONE MORE ATTEMPT TO CLEAN OUT BACK TO BOTTOM. IF UNSUCCESSFUL IN THIS ATTEMPT AND UNABLE TO RETURN WELL TO PRODUCING STATUS, WILL THEN PROCEED TO PLUG AND ABANDON AS PER OUR SUNDRY NOTICE OF 2-9-96.

ALL WORK TO BE PERFORMED WILL COMMENCE WITHIN THE NEXT 30 DAYS.

Call the BLM - Hobbs Office (505) 393-3612 one day prior to commencing the work.

18. I hereby certify that the foregoing is true and correct

SIGNED C.E. LARUE TITLE C.E. LARUE OPERATOR

DATE 12-27-96

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ARMANDO A. LOPEZ

TITLE PETROLEUM ENGINEER

DATE 1/27/97

CONDITIONS OF APPROVAL, IF ANY:

The above work shall be commenced within 30 days from this approval. If the attempt to return the well to producing status fails the well shall be plugged immediately. No further extensions to TA the well will be approved.

See Instructions on Reverse Side