

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO O. C. C.
SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029403(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

TR. 1

8. FARM OR LEASE NAME

Pearsall Queen Sand Unit

9. WELL NO.

1 -

10. FIELD AND POOL, OR WILDCAT

Pearsall Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 5, T18S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

N.Mex.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C.E. LaRue & B.N. Muncy, Jr.

3. ADDRESS OF OPERATOR

P. O. Box 196 Aretsia, New Mexico 88210

4. LOCATION OF WELL. (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980 FNL & 660 FEL; Section 5, T18S, R32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

3858 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) plumbing for casing leak survey ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Installed necessary plumbing for casing leak survey.

Casing hanger was open to air between the oil string and surface. A one inch line was assembled to surface with a one inch 2000# valve. As per instructions of USGS rep.

Inspected and approved by Ms. W. Kelly, March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Overseer

DATE

(This space for Federal or State office use)

APR 24 1979

APPROVED BY

TITLE

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

CONDITIONS OF APPROVAL, IF ANY:

