## NEW MEXICO OIL CONSERVATION COMMISSION

## MISCELLANEOUS REPORTS ON BUILDE OCC

Submit this report in triplicate to the Oil Conservation Commission Distance Office within tendays after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shorting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

## Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	REPORT ON SANDFRAC X	

## January 10, 1955, 4213 Ranier Court, Fort Worth-9, Texas

Following is a report on the work done and the results obtained under the heading noted above at the PHI PPS OIL CO.

	PHIPPS OIL CO.	H. W. WALKER Well No.	1
RE/A ME/A	Company or Operator	Lease Well NO	
		<u>т. 18-8</u> , <u>к. 32</u> .	
PEARBALL	Pool		

The dates of this work were as follows: Started pulling reds 12-29-54, Cempleted 1-8-1955

Notice of intention to do the work was (was not) submitted on Form C-102 on **December** 7, 19.54, and approval of the proposed plan was (**percenter** obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

12-30-54 12-31-54 1-1-1955 <b>X2X</b> 1-2-55 1-3-55 1-4-55	Sand pumped from 369 Sand pumped 3695-370 Sand pumped 3690-370 Sand pumped to 3700' Ran 3-1/2" USE J-55 Safety Release, Inver with 10,000 gallens 1 3-1/2" USE tubing. With with 2000%, and Pumped in 240 bbls sa 5 minutes, 2600% end and 2700% last 5 minu 2600%. Pumped in 12	O' O' , ran casing seraper, ran 3-1/2" J-55 Tubing Tubing to 3600' with 3-1/2" x 7" Larkin rted Neeseal Packer at 3600', and treated Dewell Sandfrac with 15,000# sand down Pumped in 100 bbls eil and broke formation formation took eil at 1800#, packer held OK. andfrac, with pressure 2400# at end of lat ef next 5 minutes, 2600# next 5 minutes, utes. Pumped in 120 bbls flush eil with bbls per min.
Garland Per	ter. George Laflin. De	ewell Incorporated, Engineers
APPROVED:	SERVATION COMMISSION	Des 011 Company, Partner I hereby swear or affirm that the information given above is true and correct. Name M.M. J. B. Philphe
	Name Title	Position PARTNER
	Date	Representing PHIPPS OIL COMPANY Company or Operator Address 4213 RANIER COURT, FORT WORTH-9. TEXAS

AL 141