

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO O. C. C.

SUBMIT IN TRIPlicate
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 064098

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C.E. LaRue & B.N. Muncy, Jr.

3. ADDRESS OF OPERATOR

P. O. Box 196 Aretsia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1980' FEL, Section 5, T18S, R34E

7. UNIT AGREEMENT NAME

TR 8

8. FARM OR LEASE NAME

Pearsall Queen Sand Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Pearsall Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 5, T18S, R34E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3835.6 gl.

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) plumbing for casing leak survey X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Installed necessary plumbing for casing leak survey.

Two inch was plumbed to surface with a braiding head connection consisting of a 2000# valve. At or above the surface, a one inch swage was connected to a one inch 2000# valve.

Inspected and approved by Ms. W. Kelly, March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

ACCEPTED FOR RECORD

APR 24 1979

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Overseer

U. S. GEOLOGICAL SURVEY

HOBBS, NEW MEXICO

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C. 20535

RECEIVED
JAN 10 1964
FBI - NEW YORK

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

DATE 10-10-83
BY SP-6 JCL/STP