

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate\*  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029403(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME TR # 2 1 C	
2. NAME OF OPERATOR C.E. LaRue & B.N. Muncy, Jr.		8. FARM OR LEASE NAME Pearsall Queen Sand Unit	
3. ADDRESS OF OPERATOR P. O. Box 196 Aretsia, New Mexico 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 915 FNL 2342 FWL; Section 5, T 18S, R 32E		10. FIELD AND POOL, OR WILDCAT Pearsall Queen	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 5, T 18S, R 32E		12. COUNTY OR PARISH Lea	
13. PERMIT NO.		14. STATE N.Mex.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3871 GL		16. COUNTY OR PARISH Lea	

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

plumbing for casing leak survey X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Installed necessary plumbing for casing leak survey.

Two inch was plumbed to surface with a braiding head connection consisting of a 2000# valve. At or above the surface, a one inch swage was connected to a one inch 2000# valve.

Inspected and approved by Ms. W. Kelly, March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Overseer

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

TITLE

APR 24 1979

CONDITIONS OF APPROVAL, IF ANY:

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

RECEIVED  
JUL 1 1970  
U. S. BUREAU OF  
MEXICO

RECEIVED  
JUL 1 1970  
U. S. BUREAU OF  
MEXICO