

NEW MEXICO OIL CONSERVATION COMMISSION

P. O. BOX 2045

HOBBS, NEW MEXICO

DATE January 21, 1958

Albert Gackle

Box 2076

Hobbs, New Mexico

RE: Plugging Reports

Gentlemen:

Form C-102, Notice of Intention to Plug, your J. D. Graham #1 7-18-32  
was ~~XXXXXX~~ not submitted. Your final plugging report, which has been  
filed on Form C-103, cannot be approved until a commission representative has  
made an inspection of the location to see:

- (1) all pits have been filled and levelled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township, range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared & cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By *Switzburg*

Oil & Gas Inspector

Fill in below and return:

J. D. Graham #1 H 7-185-32 is ready for your inspection and approval.  
Lease Well No. Unit S-T-R

Albert Gackle, Operator  
Operator

Paul S. Johnston  
Name and title

*E. [unclear]*

*10 Dec 70*