

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-04371-A
2. Name of Operator Anadarko Petroleum Corporation	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Drawer 130, Artesia, New Mexico 88211-0130	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 1930' FWL Sec. 22 - T18S - R32E <i>unit K</i>	8. Well Name and No. Querecho Plains Unit
	9. API Well No. 1
	10. Field and Pool, or Exploratory Area Querecho Plains Penn
	11. County or Parish, State Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Previous operator (Gary L. Bennett) filed a Notice of Intent to Recomplete in the Morrow. Mr. Bennett never filed a Subsequent Report.

Anadarko could not dedicate the necessary 320 acres needed to produce from the Morrow zone. Nor could we verify previous work done by Mr. Bennett during any attempted recompletion which he might have undertaken.

Therefore, on approximately the 1st of October 1990, Anadarko received verbal permission from Shannon Shaw (Carlsbad BLM) & Evelyn Downs (Hobbs NMOCD) to abandon the Morrow zone and to return to the Strawn zone (if indeed Mr. Bennett had recompleted in the Morrow). Shannon Shaw said he would contact Mr. Bennett to obtain a Subsequent Morrow recompletion (if appropriate). Evelyn Downs said that Anadarko should file this subsequent report showing the downhole conditions (as we found them), plus a detailed accounting of our activities thereafter (showing any changes).

1. (10/04/90) RU Wireline truck. Found tubing crimped or collapsed @ 12,284'.
2. (10/08/90) RU pulling unit. Could not unset pkr.
3. (10/09/90) Unlatched on/off tool @ 12,419'.

14. I hereby certify that the foregoing is true and correct

Signed *[Signature]* Title Area Supervisor Date 11/07/90
(This space for Federal or State office use)
Approved by _____ Title _____ Date _____
Conditions of approval, if any: _____