

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 029446

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <u>water well</u> X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

W.H. Baskin

Midland, Texas, September 28, 1945

Well No. 2 is located 1980 ft. from NE line and 1980 ft. from W line of sec. 22NW 1/4 Sec. 22
(1/4 Sec. and Sec. No.)19-S
(Twp.)33-E
(Range)N.M.P.M.
(Meridian)Tonto
(Field)Lea
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3635 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to total depth of 3593' without encountering oil or gas production and the lower portion of the hole was plugged back into the 8-5/8" casing, which was then perforated from 810' to 700', completing as a water well. Since this water well was no longer needed, it has been salvaged plugged and abandoned in the following manner. Attempted to part and pull the 8-5/8" casing beginning at 1000', but it could not be parted and pulled below 454'. After pulling this 454' of 8-5/8" casing the hole was filled with heavy mud and a 40-sack cement plug spotted to protect the water sand (810'-700'). The customary 4" pipe marker was cemented in the top of the hole with 20 sacks, leaving all 13-3/8" casing tubing. Above work was completed 8-24-45, and the location is now cleaned up and ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE TEXAS COMPANYAddress Box 1270Midland, TexasBy W.H. BaskinTitle Drig. & Prod. Foreman