
## (SUBMIT IN TRIPLICATE)

U.S. Land Office Las Cruces

Lease or permit No. 029446

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY



## SUNDRY NOTICES AND REPORTS ON WELLS

(INDICATE ABOVE BY CHECK M	URE OF REPORT, NOTICE, OR OTHER DATA)
IOTICE OF INTENTION TO ABANDON WELL	
OTICE OF INTENTION TO PULL OR ALTER CASING	 SUPPLEMENTARY WELL HISTORY
OTICE OF INTENTION TO SHOOT OR ACIDIZE	 SUBSEQUENT REPORT OF ABANDONMENT
OTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF REDRILLING OR REPAIR
OTICE OF INTENTION TO TEST WATER SHUT-OFF	 SUBSEQUENT REPORT OF ALTERING CASING.
IOTICE OF INTENTION TO CHANGE PLANS	 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
OTICE OF INTENTION TO DRILL	 SUBSEQUENT REPORT OF WATER SHUT-OFF

		Midland, Texas, January 16 19				
V. H. Baskin Well No. 3 is	located 660 ft.	from S line	and 660 ft. from	W line of sec	23	
SW4 SW4 Sec. 23	19 <b>-</b> S	33-E	N.M.P.M.	•		
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	**		
Conto	Lea	Lea		w Mexico		
(Field)	(Co	(County or Subdivision)		(State or Territory)		

The elevation of the derrick floor above sea level is 3623 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth, 3693' - Lime

16" casing cemented at 32' with 30 sacks; 8-5/8" cemented at 1420' with 100 sacks. Top of salt, 1490'; base of salt, 3050'.

This well has been drilled to 3693' without encountering oil or gas production. Sulfur water was encountered at the bottom of the hole, which filled it to a depth of 600'. Therefore, we desire to plug and abandon this well as follows:

(See attached sheet)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.						
	The Texas Company					
Address	Box 1270					
	Midland, Texas	By Ollo Cofacece				
		Title Drlg. & Prod. Foreman				