

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 029446  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, March 20, 1945

G. R. Baskin  
Well No. 3 is located 660 ft. from N line and 660 ft. from E line of sec. 23  
S  
SW 1/4 Sec. 23 19-S 33-E N.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Tonto Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3623 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to total depth of 3693' without encountering oil or gas production, and has been abandoned, plugging as follows. A cement plug of 70 sacks was spotted in bottom of hole from 3693' to 3450'. Hole was filled with heavy mud and the following cement plugs spotted: 20 sacks, 3120-3050' (at base of salt), and 30 sacks, 1470-1390' (top of salt and in bottom of 8-5/8" casing). The 8-5/8" casing was parted and pulled at 686', a cement plug of 20 sacks was spotted at 828-800', and 20 sacks of cement spotted at 700-672' (in top of parted 8-5/8" casing) to adequately protect fresh water sand at 700'-800'. The required 4" pipe marker was cemented in the top of the hole with 20 sacks. Above work was completed 1-21-45 and location is now cleaned up and ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE TEXAS COMPANY

Address Box 1270  
Midland, Texas

By \_\_\_\_\_  
Title District Superintendent.