(SUBMIT IN TRIPLICATE)


Land Office

Unit

New Mexico

Lease No.

073240



DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

RECEIVED

MAR 7 1962

SUNDRY NOTICES AND REPORTS ON WELLS D. C. C. ARTESIA, OFFICE NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF WATER SHUT-OFF MOTICE OF INTENTION TO CHANGE PLANS SUBSEQUENT REPORT OF SHOOTING OR ACIDITING MOTICE OF INTENTION TO TEST WATER SHUT-OFF SUBSEQUENT REPORT OF ALTERING CASING MOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR MOTICE OF INTENTION TO SHOOT OR ACIDIZE SUBSEQUENT REPORT OF ABANDONMENT. MOTICE OF INTENTION TO PULL OR ALTER CASING SUPPLEMENTARY WELL HISTORY NOTICE OF INTENTION TO ABANDON WELL .

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	2	.	eptamber 22.	, 1961
Signal Ross Well No. #2 is located	1980. ft. from . N		2004 ft. from	line of sec. 30
#E/4 #E/4 #ec. 30 (H Bec. And Sec. No.)	198 (T-P.)	S3R (Range)	Meridian)	
South TouteseYstes (Field)	(County	na y or Bubdivision)	New M (State or 1	exico eritory)
The elevation of the derrick flo	or above sea l	evel is fi	t.	
	DETA	ils of work	<u>.</u>	
(State names of and expected depths to obj	setive sande; sheer s	ines, woighte, and longi	the of proposed centres indi-	cate mudding jobs, coment-

ine waints, and all other important proposed work)

On Sept. 22, 1961, wall was plugged as follows:

- 12 sacks cement (100°) from 2975-3075.
- 22 macks sement (100") from 2630-2730.
- 30 sacks coment (100°) from 1350-1450.
- 35 marks coment (100°) from 50-150.
- 10 sacks coment at surface.

RECEIVED

SEP 22 1961

U. S. GEGLOGICAL SURVEY ARTESIA, NEW MEXICO

i wadenstand that this plan of week must receive approval in writing by the Goological Survey before operations may be commenced.			
Company	William A. & Advand R. Hudage		
Address	1510 First Mathemal Audiding	1217h	
	Fort Worth, Taxes.	By Rack I may	
. 4,5 ,		Title Consulting Engineer	