

Form 9-331a
(Feb. 1961)Budget Bureau No. 42-R358.4.
Form Approved.

(SUBMIT IN TRIPLICATE)

Land Office New MexicoLease No. 073240Unit AUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 4, 1962

Signal Ross
Well No. #5 is located 330 ft. from [N] line and 990 ft. from [E] line of sec. 30
NE 1/4 NE 1/4 (1/4 Sec. and Sec. No.) 19E (Twp.) 33E (Range) N.M. (Meridian)
South Tonto-Yates (Field) Lee (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On November 7, 1962, 13-3/8" O.D. casing was cemented at 75' with 100 sacks. No water was encountered.

On November 11, 10-3/4" casing was set at 464'. This was pulled on November 28.

On November 14, 8-5/8" casing was set at 985'. This was pulled on November 28.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Perry R. Bass - Little Eddy Unit
William A. & Edward R. Hudson, AgentAddress 302 Carper BuildingArtesia, New Mexico

By

Ralph L Gray

Title

Consulting Engineer.