Submit 3 Copies to Appropriate District Office	State of New Me Ene Minerals and Natural Re		Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30 025 02156
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B 4118
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OIL WELL WELL	OTHER S.W.	Disposal	Phillips Lea
2. Name of Operator			8. Well No.
Rover Operating, Inc.			4
3. Address of Operator			9. Pool name or Wildcat Vacuum
903 18th Street, Suite 224, Plano, Texas 75074			Grayburg - San Andres
	330 Feet From The <u>South</u>		
Section 31	Township 175 Ra		NMPM Lea County
4096 Ground			
11. Check	Appropriate Box to Indicate I		eport, or Other Data
			SEQUENT REPORT OF
		REMEDIAL WORK	
	CHANGE PLANS		
PULL OR ALTER CASING			
OTHER: Monitor Casin	ng Pressure 🛛 🗴	OTHER:	· · · · · · · · · · · · · · · · · · ·
12 Describe Proposed or Completed One	minne (Clearly state all pertinent details as	ad aive pertinent dates inclu	ding estimated date of starting any proposed

12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Well has two small leaks. As long as there is no pressure applied to the casing no fluid leak-off should occur. The source of pressure would be from the injection pressure within the tubing string. The entire string including the packer isprotected by a hard plastic tube cemented inside each joint of tubing.
- 2) Rover proposes to install a pressure recorder on the annulus with an eight day clock. The charts will pick up any pressure build up in the casing as a result of a tubing or packer failure. If this should occur the well will be immediately pulled and repairs made. The weekly charts will be submitted to the District I office promptly.
- 3) This recorder will be installed in the first week of September, 1997

I hereby certify that the information powe is true and complete to the best of my know SIGNATURE	nedge and belief. President	DATE 08/29/97 972 TELEPHONE NO.422-9029
(This space for State Use) ORIGINAL SIGNED BY CHERS WILLIAMS DISTRICT I SUPERVISOR APPROVED BY	TTTL#	DATE