


HOBBS OFFICE COPY

APPROVED (SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.



JUL 28 1960

F. W. STANLEY
DISTRICT ENGINEER

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lease No. LC-064227
Unit

RECEIVED

JUL 19 1960

U. S. GEOL
NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gulf-Federal

July 19, 1960

Well No. 1 is located 330 ft. from N line and 330 ft. from W line of sec. 15
SW/4 SW/4 Sec. 15 T19S R34E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3778.3 ft.

*Inspected 7-26-60
O.K. for abandonment
J. L. G.*

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned 5/16/60 TD 5186' 8-5/8" csg cemented at 107'

NOTED

Plugged as follows:

JUL 18 1960

- 10 sx plug in top of 8-5/8" with regulation marker
- 30 sx at base of 8-5/8" top of plug 100'
- 25 sx plug top of salt-top of plug 1700'
- 15 sx plug at base of salt-top of plug 3200'
- 15 sx plug at top of Queen-top of plug at 4680'
- 15 sx plug at top of Penrose -top of plug at 4980' - 4980-5030'

GORDON

Location has been cleaned and levelled and regulation marker has been set.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W. G. KIRKLIN & ORMAND BROS.

Address c/o Oil Reports Box 763 Hobbs, New Mexico

By

Agent

Title