

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 063679

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Julia Brainard

January 16, 1950

Well No. 1 is located 1980 ft. from N line and 660 ft. from E line of sec. 19

SE 1/4 of Sec. 19 19-S 34-E NTP
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
"Wildcat" Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3703 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PLUGGED & ABANDONED- Total Depth 5010 Feet. Completed plugging job on January 14, 1950. Hole filled with mud laden fluid- 10.5% mud. Spotted 180 sacks cement at 4955 feet, cement back to 4487 feet. Spotted 110 sacks cement at 4950 feet, cement back to 3764 feet. Spotted 150 sacks cement at 3550 feet, cement back to 3417 feet. Spotted 150 sacks cement at 3417 feet, checked top of cement with drill pipe- found top at 3047 feet in 9-5/8" casing. Shot 9-5/8" casing off at 523 feet and pulled 501' feet. Spotted 150 sacks cement on top of 9-5/8" casing and this cement came back up inside of 13-3/8" casing. Spotted 25 sacks cement at surface inside of 13-3/8" casing. Hole marked with 4" pipe filled with ~~drill~~ cement this marker placed at least six (6) feet in ground and at least four (4) feet above ground. Location levelled and cellar filled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company RICHARDSON & BASS

Address P.O. Box 1178

Monahans, Texas

By E. W. Longenecker

Title Superintendent.