Form 9-891 a (Adarch 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget	Baresa .	No.	42-R3	83.1
Approv	al expire	1 1-	20-49.	

Land Office Las Cruces

Lass No. 063679

Unite

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	- -	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Julia Brainard	***********	December 27	, 19.4.2.
Well No is loca	ted 1980. ft. from ${N \choose S}$ line	e and 660 ft. from \mathbb{R} line of	sec. 19
SE/4 of Sec. 19	19-S 34-E (Twp.) (Bange)	MP (Meridian)	
Wildcat	Lea	New Mexico	
(Field)	(County or Subdivision)	(State or Territory)	
		_	

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comentating points, and all other important proposed work)

Ran 3,327.13 feet of 9-5/8" OD 40# casing set at 3,341.88 feet with 1,200 sacks cement. Plug down 4:10 A.M. 12/21/49. Top of cement behin casing- temperature survey- 570 feet.

Tested casing with 1,500 pounds pressure for 30 minutes- no pressure drop. Drilled plug 9:45 Λ .M. 12/26/49. Top of hard cement inside casing 3,236 feet.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	Richardson and Bass			
Address	P.O. Box 1178, Monahans,	Taxas		
		By Coloradort Title Superintendent		
	***************************************	Title Superintendent		