



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las CrucesLease No. L C 068310Unit Lease

1957 MAR 7 PM 3:12

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 26, 1957

Well Gillespie "A"

Well No. 1 is located 2310 ft. from [N] line and 2310 ft. from [W] line of sec. 28NW/4 Section 28

(1/4 Sec. and Sec. No.)

19S

(Twp.)

34E

(Range)

NMPM

(Meridian)

Wildcat

(Field)

Lee

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3716 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 9:30 PM 2-23-57. Drilled 15 inch hole to 367 feet Red Bed.  
Cemented 10 3/4 inch 32.75# casing at 366 feet with 300 sacks neat cement.  
Plug down 1:30 PM 2-24-57. Cement circulated to surface. After WOC 24  
hours pressure tested casing with 500 psi for 30 minutes. Test O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Drilling & Exploration Company, Inc.Address Box 2075Hobbs, New MexicoBy D. E. MillerTitle Division Prod. Superintendent

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes that this is crucial for ensuring transparency and accountability in the organization's operations.

2. The second part of the document outlines the various methods and tools used to collect and analyze data. It mentions the use of surveys, interviews, and focus groups to gather information from stakeholders. Additionally, it discusses the use of statistical software to process and interpret the data.

3. The third part of the document describes the results of the data collection and analysis. It highlights the key findings and trends observed in the data. For example, it notes that there is a significant increase in the number of transactions over the past year, which is a positive indicator of growth.

4. The fourth part of the document provides a detailed analysis of the data, including a breakdown of the results by category and a comparison with previous periods. It also includes a discussion of the limitations of the data and the potential for future research.

5. The fifth part of the document concludes the report by summarizing the main findings and providing recommendations for future action. It suggests that the organization should continue to monitor its performance and make adjustments as needed to ensure long-term success.

6. The final part of the document includes a list of references and a bibliography, providing sources for the data and information used in the report.