

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	X	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

March 1, 1949

Roswell, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Barnett & Hanson

State

Well No. 1-A in the _____

Company or Operator

Lease

SW 1/4 SE 1/4

of Sec. 19

T. 17S

R. 35E

N. M. P. M.,

Vacuum

Field,

Lea

County.

The dates of this work were as follows: _____

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____ 19____and/or approval of the proposed plan was ~~(cross out)~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well swabbed at rate of 66 bbls oil per day before acidizing

2-9-49 - 2" tbg was run to PB depth of 4667', with pkr at 4566 & perf
at 4662-4665'. Formation was treated with 1000 gals. of
20% acid. Pkr failed after first 600 gals was injected

after acid - well swabbed 90 bbls oil daily

2-15-49 - Treated with 2500 gals. 15% acid.

After acid - well swbd and flwd 8-10 bbls oil per hour.

2-16-49 - Treated with 5000 gals. 15% acid.

After acid - flwd 99 bbls oil in 7 hrs 45 min.

Witnessed by John A. Barnett

(Work done by The Western Company)

Name

Company

Title

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

15th day of March 1949

Name John A. Barnett

Position Co-Partner

Notary Public

Representing Barnett & Hanson
Company or Operator

My commission expires 6/6/57

Address P.O. Box 670
Roswell, New Mexico

Remarks:

APPROVED

Date MAR 1 1949

Title

Handwritten text at the bottom left of the page, possibly a signature or date.