

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

COPIES RECEIVED	
DISTRIBUTION	
DATE	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR REEQUIP A WELL IN A DIFFERENT RESERVOIR.
SEE INSTRUCTIONS FOR REPORTS ON WELLS FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

MARATHON OIL COMPANY

Address of Operator

P.O. BOX 2409 HOBBS, NEW MEXICO 88240

Location of Well

UNIT LETTER F 1980 FEET FROM THE West LINE AND 1980 FEET FROM
THE North LINE, SECTION 19 TOWNSHIP 17S RANGE 35E NMPAL.

13. Elevation (Show whether DE, RT, CR, etc.)

GL 3983' ; KDB 3993'

5a. Indicate Type of Lease

State ☒ Free ☐

5. State Oil & Gas Lease No.

K-6023

B-2245

7. Unit Agreement Name

8. Farm or Lease Name

Staplin State a/c 2 Com.

9. Well No.

1

10. Field and Pool, or Wildcat

Vacuum Abo, North

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

FULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Pipe casing bradenheads to surface ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dug well cellar out to expose all casing bradenhead outlets.
2. Installed 1" piping from 2" valve on outlet on each bradenhead to a point above ground level. Installed 1" valve on upper end of piping.
3. Ran bradenhead pressure and blew down surface string. Survey indicated no leak.
4. Piping arrangement, open position of 2" valve and closed position of 1" valve, inspected and approved by New Mexico Oil Conservation Commission Deputy Oil and Gas Inspector, Nathan Clegg.

Bradenhead Size

9-7/8"

7"

Bradenhead

Valve Location

Northwest side of well (1")

South side of well (2")

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Engineer Technician

DATE 7/7/76

Original Signed by
John Runyan

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DIST.: RPS, JOH, FILE COPL

JUL 12 1976