

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02845
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2264-1
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2155
8. Well No.	084
9. Pool name or Wildcat	VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter J : 1175' Feet From The SOUTH Line and 2500 Feet From The EAST Line Section 21 Township 17 S Range 35 E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3956.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/01/95 MIRU SIERRA WELL SERVICE DDU #3, NOTIFY NMOC OF INTENT TO PLUG.  
ND WELLHEAD, NU CLASS 1 MANUAL BOPE, PU 5-1/2" CIBP, WS, SET CIBP @ 4345'.  
MIXED & CIRC 10# MUD LADEN BRINE, SECURED WELL SDON.  
5/02/95 NOTE: ALL CEMENT PLUGS CLASS "C", 14.8 PPF & 1.32 CFPS.  
PUMP PLUG #1, 35 SXS, INTERVAL 4345'-4008', PULLED UPHOLE TO 3003'.  
PUMP PLUG #2, 25 SXS, INTERVAL 3003'-2763', PULLED UPHOLE TO 1782'.  
PUMP PLUG #3, 25 SXS, INTERVAL 1782'-1542', POOH W/ WS.  
RU WL & PERF 5-1/2" SCG @ 400', RD WL.  
SQZD PLUG #4, 100 SX, (40 SX C NEAT & 60 SX C + 3& CACL), INTERVAL 400'-300'.  
DISPLACE CMT TO 300', DID NOT CIRCULATE CMT TO SURFACE. WOC.  
RU WL, RIH TAG TOC PLUG #4 @ 250', RD WL.

(OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. M. Sanders TITLE Regulation Specialist DATE 5/10/95  
TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

IC

✓  
KBP

5/02/95 PULLED UPHOLE, PERF"D 5-1/2" csg @ 250', RD WL.  
SØZ'D PLUG #5,65 SXS CLASS "C" NEAT, INTERVAL 250'-150'.  
DID NOT CIRC CMT TO SURFACE, SECURED WELL, SDON.

5/03/95 RU WL & TAG PLUG #5 @ 111', PERF @ 110', RD WL.  
PUMP PLUG #6, 55 SXS CLASS "C", 14.8 PPG & 1.32 CFPS,  
INTERVAL 110'-3', CLOSED BRADEN HEAD VALVES, SØZ'D  
25 SXS, CEMENT CIRCULATED OUT BACKSIDE OF 8.625" CSG.  
RDMO SIERRA WELL SERVICE RIG #3,  
WELL IS PLUGGED AND ABANDONED.

RECEIVED

MAY 1 1995  
OFFICE