

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02859
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1713
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2335
8. Well No.	002
9. Pool name or Wildcat	VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3933' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter M : 330 Feet From The SOUTH Line and 990 Feet From The WEST Line
Section 23 Township 17-S Range 35 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3933' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: SWAB TEST, REACTIVATE ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/03/95 MIRU DDE, COOH W/RODS & PUMP, NU BOPE, COOH W/TBG, TIH & TOH W/CSG SCRAPER, Sisd.
5/04/95 GIH W/TBG & PKR, SET PKR @ 4089' & END OF TBG @ 4480'. TEST CSG TO 550# O.K.. RU SWAB
RECOVER 44 BBLS WATER, Sisd.
5/05/95 OPEN WELL, RECOVER 29 BBLS WATER, 8 BBLS OIL, RESET PKR @ 3710', Sisd.
5/06-07/95 CREW OFF
5/08/95 MIRU HES, PUMP 1000 GALS ACID, 1000# ROCK SALT, W/1000 GALS GELLED BRINE, RDMO HES,
OPEN WELL, RU SWAB, RECOVER 51 BBLS WATER, TRIP TBG & PKR, Sisd.
5/09/95 MIRU HES, PUMP 3000 GALS FERCHECK 15% ACID, 1000# ROCK SALT, 600 GALS BELLED BRINE,
RDMO HES, OPEN WELL, RU SWAB, RECOVER 160 BBLS WATER, Sisd.
5/10/95 REL PKR, COOH W/TBG & PKR, GIH W/TBG, ND BOPE, FLANGE UP WELLHEAD, GIH W/PUMP & RODS
RDMO DDU, PUMP NO TEST.
5/11/95 PUMP 24 HRS, NOT TEST.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Regulation Specialist DATE 5/22/95

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 25 1995

CONDITIONS OF APPROVAL, IF ANY:

5/12-13-14-15/95 PUMP 24 HRS, NO TEST.
5/16/95 PUMP 24 HRS, NO TEST.
5/17/95 PUMP 24 HRS, NO TEST, HOT OILER HOT WATERED WELL.
5/18/95 PUMP 24 HRS, TEST 19 BOPD, 30 BWPD, 0.2 MCF 79% CO2.
5/19/95 PUMP 24 HRS, TEST 14 BOPD, 22 BWPD, 1.3 MCF 67.7% CO2.
5/20/95 PUMP 24 HRS, TEST 16 BOPD, 14 BWPD, 2.7 MCF 54.7% CO2.
COMPLETE DROP FROM REPORT