

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Ross Brunner				Address 702 V & J Tower - Midland, Texas			
Lease Southern Petroleum State		Well No. 1	Unit Letter A	Section 24	Township 17 S	Range 35E	
Date Work Performed 7-30-60		Pool Wildcat			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Drilled to total depth of 9604'
 Pulled 1896' of 8' 5/8" intermediate casing.
 Set cement plugs as follows:

1. 25 sacks @ 9600'
2. 25 sacks @ 6470'
3. 50 sacks @ 4760'
4. 25 sacks @ 3002'
5. 25 sacks @ 1896'
6. 10 sacks @ surface

Erected a 4" X 4' permanent marker

Witnessed by A. C. Brunner	Position Production Supt.	Company Ross Brunner
--------------------------------------	-------------------------------------	--------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>Leslie A. Clement</i>	Name <i>A.C. Brunner</i>
Title	Position Production Supt.
Date	Company Ross Brunner