

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction
verse side)

Form approved.
Budget: Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM020491

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Lovington Unit

8. FARM OR LEASE NAME

9. WELL NO.

38

10. FIELD AND POOL, OR WILDCAT

West Lovington Upper San Andres

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA

Sec. 3 T17S-R36E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Greenhill Petroleum Corporation

3. ADDRESS OF OPERATOR

11490 Westheimer, Ste., 200, Houston, TX 77077

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter M, 660 FSL & 660 FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3878 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Temporary Abandon

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-4-91 Ran Baker AD-1 on 181 Jts of new IPC tbg. Set pkr & pressure tested csg.
& tbg. 500#. Held OK. Attached find the chart summarizing the test.
440 psi



18. I hereby certify that the foregoing is true and correct

SIGNED

Michael Murphy

TITLE Land Manager-Permian Basin

DATE 5-23-91

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE 6-6-91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

L PU # 38

660 FSL
660 FWL
Sec. 3, T115-R36E

5/4

1991

BR 2221

RECEIVED

JUN 10 1991

030
HOBBS OFFICE