

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, N. M.
Land Office **61293**
Lease No. _____
Unit **RECEIVED**
Federal Ruby S. Crosby.
NOV 17 1944
HOLERS OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas **November 15, 1944**

Well No. **1** is located **1900** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **4**
Center of SW 1/4 of NW 1/4
of Section 4
Turner **2-17-S** **R-36-E**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Turner **Lee** **New Mexico.**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3900** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested 10-3/4" casing with 7000# cold water pressure and drilled cement plug at 2:00 AM 11-14-44. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Humble Oil & Refining Company.**

Address **Box 1400,**
Midland, Texas.

By **[Signature]**
Title **Asst. Div. Superintendent.**