

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106) 2 51

COMPANY John L. Hannon, 511 Midland Savings Building, Midland, Texas
(Address)

LEASE State E-3744 WELL NO. 1 UNIT D S 31 T 17-S R 36-E
DATE WORK PERFORMED 6-25-61 POOL Wildcat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Pulled 1355.13' of 5/8" casing, placed 25 sacks cement in and out of stub. Set 10 sacks cement plug in top of 13 3/8" surface casing.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
	(Company)	

OIL CONSERVATION COMMISSION
Name John W. Kungun
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name A J Mayberry
Position Clerk
Company John L. Hannon