

OIL CONSERVATION DIVISION
 P. O. BOX 2088
 SANTA FE, NEW MEXICO 87501

Form C-103
 Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Name of Operator Chevron U.S.A. Inc. Address of Operator P.O. Box 670 Hobbs, NM 88240 Location of Well UNIT LETTER K 1980 South 1980 West 13 17S 38E T1E LINE. SECTION TOWNSHIP RANGE NMPM.	7. Unit Agreement Name 8. Form or Lease Name H.V. Black 9. Well No. 1 10. Field and Pool, or Wildcat Knowles Devonian South 11. Elevation (Show whether DF, RT, GR, etc.) 3685' GL 12. County Lea
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

DRILL REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
FORABLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/> Repairing leak

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Found casing leak 5792'-5854'. Cemented with 200 sacks class "C" 16% Gel, 3% Salt, .2% WR-2, .6% CF-14 and 235 sacks class "C" .6% CF-14 tailed with 100 sacks class "C" .1% TF-4 with returns to surface. Drilled out cement and retainer. Swabbed tubing and casing down to 5830'. No fluid entry after waiting 1 hour. Equipped to pump. Returned to production. Work performed 10/12/86 - 10/19/86.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by Paul Kautz Geologist	TITLE: Drilling Superintendent DATE: 10-21-1986
SIGNED BY: Paul Kautz TITLES OF APPROVAL, IF ANY:	DATE: OCT 23 1986