

Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 063559

Unit N

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	X	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mex. Nov. 30, 1950

Thos. B. Cox

Well No. 1-X is located 510 ft. from SW line and 1685 ft. from W line of sec. 17

SE 1/4 Sec. 17
(1/4 Sec. and Sec. No.)

183
(Twp.)

32E
(Range)

N 1/2
(Meridian)

Young
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3751 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD is 3778. Oil sands were encountered 3752-60' and 3767-71'. Oil production has declined to about 35 bbls. per day. In view of previous experience in this pool with plugging of formation with a gyp deposit, we propose to shoot the pay with a Burch marble shot to clean the sand face. Hole will then be cleaned out with sand pump and well put back to pumping.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BUFFALO OIL COMPANY

Address 203 CARPER BUILDING

ARTESIA, NEW MEXICO

By J. H. Ellis

Title Vice President