

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Artesia, New Mexico May 13, 1949
Place Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Buffalo Oil Company Thos. S. Cox Well No. 2 in the
Company or Operator Lease

SW $\frac{1}{4}$ SW $\frac{1}{4}$ of Sec. 17, T. 18 S, R. 32 E, N. M. P. M.,
Young Field, Lea County.

The dates of this work were as follows: April 30, 1949Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____ 19____

and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.) See below

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well was drilled to a depth of 3798' and no shows of oil, gas or water were found. Approval to plug well was obtained from the U. S. Geological Survey. 5 $\frac{1}{2}$ " casing was parted at 2980'. Hole was filled from surface to total depth of 3798' with mud and 5 $\frac{1}{2}$ " casing was then pulled. Tubing was run back in hole to 2980' and 10 sacks of cement was spotted at this point. 20 sacks of cement was then spotted at 1022' in bottom of 8-5/8" casing. 8-5/8" casing was parted at 371 and pulled. A 10 sack surface plug of cement was spotted in hole and a proper marker made of 4" pipe was inserted to mark location of hole.

Witnessed by Ralph L. Gray, Buffalo Oil Co. Ass't Supt.
Name Company Title

Subscribed and sworn before me this 13th

I hereby swear or affirm that the information given above is true and correct.

_____ day of May, 19 49Name J. H. LewisPosition Vice PresidentRepresenting Buffalo Oil Company
Company or OperatorMy commission expires June 30, 1951Address Box 517, Artesia, N. M.

Remarks:

Name

Vice President

Title