



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 064175-A

Unit C

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Sand-Frack Treatment</u> <u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 17, 1957

Well No. 11 is located 2310 ft. from N line and 2310 ft. from E line of sec. 17

N30W T 16 S R 32 E 10MPH  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Young Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3767 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sand-frack Treatment;

To treat casing perforations via casing with 32,354 gas lease oil and 20,000 40/60# 30,000 #20/40 sand.

Casing Cap.	99.73	Max trtg. pressure	35.00
Brake down	40.00	Min trtg. pressure	18.00
Trtg. to frac.	762.00	Injection rate frac.	54.4
Flush	89.73	Injection rate on	
Over flush	35.27	flush	45.0
		over all injection	
Total to recover	937.00	rate	47.7

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company McCurdy-Tremell Joint Vent.

Address 213 Carter Bldg.

Artista, New Mexico

By Harold L. Tunny

Title \_\_\_\_\_