

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Midland, Texas

February 20, 1945

Place

Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

The Texas Company's State of New Mexico "AF" Well No. 1 in the _____
 _____ Company or Operator _____ Lease _____
NW 1/4 S 1/4 of Sec. 28, T. 17-S, R. 34-E, N. M. P. M.,
Vacuum Field, Lea _____ County.

The dates of this work were as follows: (See below)

Notice of intention to do the work was (~~was~~) submitted on Form C-102 on August 26, 1944
 and approval of the proposed plan was (~~was~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Total Depth, 4972' - Lime. 5-1/2" casing cemented at 4076' with 300 sacks; 8-5/8" cemented at 892' with 300 sacks.

The hole was filled with heavy mud and a cement plug of 35 sacks was spotted in the bottom of the hole from 4972' to 4660'. A 20-sack cement plug was spotted in the bottom of the 5-1/2" casing, from 4150' to 4000'. The 5-1/2" casing was parted and pulled at 1320', and a
 (See reverse side)

Witnessed by _____ Name _____ Company _____ Title _____

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

20th day of February, 1945

Name J. T. Shupert

Mary L. Corbin Mary L. Corbin
 Notary Public

Position District Superintendent

Representing The Texas Company
 Company or Operator

My commission expires 6-1-45

Address Box 1270 Midland, Texas

Remarks:

Roy Garbrough
 Name
 Title

plug of 20 sacks of cement spotted from 1340' to 1260' in the top of the parted 5-1/2" casing). A cement plug of 20 sacks was spotted in the bottom of the 8-5/8" casing from 920' to 860', and a 4" pipe marker extending 4' above the ground was cemented in the top of the hole with 10 sacks. Completed salvaging, plugging and abandoning December 7, 1947.