STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT						
OIL CONSERVATION DIVISION	Form (* 101					
DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78					
FILE SANTA / E, NEW MEXICO 6/301	Sa. Indicate Type of Lease					
	State X For					
OPERATOR	5. State Oti & Gun Lease No. B-1398-5					
SUNDRY NOTICES AND REPORTS ON WELLS						
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FUR PROPOSALS TO DRILL OR TO DEEPLN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)						
1. WILL A GAB OTHER- Reenter to replug	7. Unit Agreement Name East Vacuum Gb/SA Unit					
2. Name of Operator	8. Farm or Lease NameEast Vacuum					
Phillips Petroleum Company Sheete Cled Co. State State	Gb/SA Unit, Tract 2109 9. Well No.					
Room 401, 4001 Penbrook, Odessa, Texas 79762	001					
4. Location of Well I 1980 South 660	Vacuum Gb/SA					
UNIT LETTER FEET FROM THE FEET FROM THE LINE AND FEET FROM						
East LINE, SECTION 21 TOWNSHIP 17-S 35-E						
WITTER DF, RT, GR, etc.)	12. County					
Not available	Lea AllIIIIII					
10. Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data T REPORT OF:					
NOTICE OF INTENTION TO: SUBSEQUEN						
PERFORM REMEDIAL WORK	ALTERING CASING					
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT X					
PULL OR ALTER CASING CASING TEST AND CEMENT JUE OTHER Replugged per OCI	<u>) Order R-5897</u>					
отися	•					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEZ RULE 1103.						
Re-entered and replugged per following procedure:						
08-04-80MI, Well Units WS Unit. Cleaned out from surface to 30'.						
08-05-80Cleaned out from 30' to 220'.						
08-06-80Ran tbg and 7-7/8" bit to 1710', stuck bit.						
08-07-80Jarred bit loose, cleaned out from 1710' to 1743'.						
08-08-11-80Cleaned out from 1743' to 3090'. Pulled tbg and bit.						
08-12-13-80Cleaned out from 3090-4460'.						
08-14-80Spotted 130 sxs Cl "H" cmt at 4460'. Pulled tbg to 3100 tbg clean. WOC.	', reversed csg and					
08-15-16-80Tagged cmt plug at 3180', spotted 200 sxs C1 "C" cmt at 3100'. WOC 6 hrs. Tagged top cmt at 2820'. Spotted 25 sxs C1 "C" cmt at 2820' and 125 sxs C1 "C" cmt at 1850'. Tagged TOC plug at 1283'. Spotted 35 sxs C1 "C" cmt at 400'. Pulled tbg to 120', circd cmt to surface w/35 sxs C1 "C" cmt. MO Well Units WS unit. Installed dry hole marker. Well P&A 8-16-80.						
BOP equipment series 900, $3000\#$ WP double w/l set blind rams and 1 se	t pipe rams (mannually					
18. I hereby certify that the information above is true and complete to the bast of my knowledge and belief.	operated).					
M. J. Mueller Senior Engineering Special	ist August 18, 1980					
And the second s	DES O GOD					

CONDITIONS	0F	APPROVAL,	١F	AN71