NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	NEW MEXICO OF CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	1	State X Fee
OPERATOR		5, State Oll & Gas Lease No.
OPERATOR		B-2519
		D=2717
	RY NOTICES AND REPORTS ON WELLS prosals to drill or to deepen of plug back to a different reservoir. Ion for permit	
1. GAS		7. Unit Agreement Name
WELL WELL	OTHER-	Vacuum Abo Unit
2. Name of Operator		8. Farm or Lease Name
Phillips Petroleum Co	mpany	Vacuum Abo Unit Btry 1
3. Address of Operator		9. Well No. Tract 6F
Room B-2. Phillips Bu	ilding, Odessa, Texas 79760	Well No. 78
4. Location of Well		10. Field and Pool, or Wildcat
	50 FEET FROM THE NOTTH LINE AND 350 FEET	
THE West HAR SECTION	ON 35 TOWNSHIP 17-S RANGE 35-E	
	JN RANGE J/ WINSHLP N	
THERODV LINE, SECTIO		(
THE LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	15. Elevation (Show whether DF, RT, GR, etc.) 3921' Gr.	12. County
16. Check A	15. Elevation (Shore whether DF, RT, GR, etc.) <b>3921 Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of	12. County Los r Other Data
	15. Elevation (Shore whether DF, RT, GR, etc.) <b>3921 Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of	12. County
16. Check A	15. Elevation (Shore whether DF, RT, GR, etc.) <b>3921 Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of	12. County Lea T Other Data JENT REPORT OF:
16. Check A NOTICE OF IN	15. Elevation (Show whether DF, RT, GR, etc.) <b>3921' Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of NTENTION TO: PLUG AND ABAHDOM REMEDIAL WORK	12. County Lea T Other Data JENT REPORT OF:
16. Check A NOTICE OF IN	15. Elevation (Show whether DF, RT, GR, etc.) <b>3921' Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of NTENTION TO: SUBSEQUENTION TO:	12. County 12. County I Con T Other Data JENT REPORT OF: ALTERING CASING
16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	15. Elevation (Show whether DF, RT, GR, etc.) <b>3921' Gr.</b> Appropriate Box To Indicate Nature of Notice, Report of NTENTION TO: PLUG AND ABAHDOM REMEDIAL WORK	12. County I Conternation of the second sec
16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	15. Elevation (Show whether DF, RT, GR, etc.) 39211 Gr. Appropriate Box To Indicate Nature of Notice, Report of NTENTION TO: PLUG AND ABAHDOM REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS COMMENCE DRILLING OPNS.	12. County I Conternation of the second sec

On <u>1-20-71</u>, MI Well WS Unit, pld rods and tbg. Ran bailer, drilled Hydromite plug from 8789' - 8795'. <u>1-21-71</u>, drilled Hydromite plug f/8795-8805'. Pushed BP to 8962'. <u>1-22-71</u>, Howce pumped in 200 BW, unable to circulate, tubing set at 8900', OE. Spotted 130 sx Trinity Inferne through tbg set at 8900', followed by 20 BW. Pulled tbg to 8000'. Pumped in 10 BW. Pulled tbg to 7500', pumped in 70 BW at 125# press. SD 30 min, pumped in 20 BW, SD 30 min. Lowered tbg to 8600'. Pumped down csg, did not reverse cement. Lowered tbg to 8650', did not circulate cement. Lowered tbg to 8700', did not circulate cement. Tagged top of cement at 8708'. Perforations 8612-8392' now effectively abandoned by cementing. Spotted 1000 gals 10% acetic acid on <u>1-23-71</u>. Ram Guns perforated casing opposite Vacuum Abo Reef selectively from 8612'-8632', and 8670-84', 34 feet, 2 shots per foot, 68 shots. Set 2-3/8" tbg at 8631' w/Baker anchor catcher on bottom. Ram rods and pump. MO Well WS unit. Restored well to production status from perfs 8612-84' in Abo Reef with PBTD of 8708'.

18. I hereby certify that the information above is true and comple	ete to the best of my knowledge and belief.			
Maner W. J. Mueller	Associate Reservoir Engineer	DATE_	1-25-7]	L
APPROVED BY	TITLE OF AND A DISTNICE .	DATE_		3 1971
CONDITIONS OF APPROVAL, IF ANY:				