SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO GRILL OR TO DEEPEN OR PLUS BACK TO A DIFFERENT RESERVOIR. 1. OIL	e
1. OIL X GAS WELL OTHER- 2. Name of Operator Marathon Oil Company 3. Address of Operator P. O. Box 2409 Hobbs, New Mexico 88240 4. Location of Well 7. Unit Agreement Name 8. Farm or Lease Name McCallister State 9. Well No. 9. Well No. 10. Field and Pool, or Wildcate	e
OIL X GAS WELL OTHER- 2. Name of Operator Marathon Oil Company 8. Farm or Lease Name McCallister Stat 3. Address of Operator P. O. Box 2409 Hobbs, New Mexico 88240 9. Well No. 9. Location of Well 10. Field and Pool, or Wildows	e
Marathon Oil Company 3. Address of Operator P. O. Box 2409 Hobbs, New Mexico 88240 4. Location of Well 10. Field and Pool, or Wildcart	e
3. Address of Operator P. O. Box 2409 Hobbs, New Mexico 88240 4. Location of Well 10. Field and Pool, or Wildcat	
4. Location of Well 10. Field and Pool, or Wildoor	
10. Field and Footy of Whitest	
UNIT LETTER K 1650 FEET FROM THE South LINE AND 1650 FEET FROM VACUUM Blinebry	
THE West LINE, SECTION 25 TOWNSHIP 178 RANGE 34E NMPM.	444
15. Elevation (Show whether DF, RT, GR, etc.) 12. County GL 4003'; KDB 4014' Lea	VIII.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	77773
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
PERFORM REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONME	17
PULL OF ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Well Status	
OTHER WELL BEAUTY	<u>LX</u> I
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pr	posed
work) SEE RULE 1103.	
 Rigged up pulling unit. Installed BOP. Pulled downhole equipment (2-1/16" tubing, 4 Camco gas lift valves, tubing divider, and Model D packer anchor/seal assembly. Ran 2-3/8" tubing to 6298' w/seating nipple @ 6261', and 5-1/2" Baker anchor catcher @ 6262'. Ran 3/4" rods and pump. 	
5. Removed BOP and installed pumping unit.6. Placed well on production.	
o. Tracea werr on production.	•
	•
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
D. 1 8. O. But and T. 1	1075
SIGNED Kaigh Skinzu / TITLE Engineer Technician DATE November 17,	19/5