

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Consolidated Oil & Gas, Inc.		Address 4150 E. Mexico Ave., Denver 22, Colorado			
Lease Shipp "A"	Well No. 1-15	Unit Letter G	Section 17	Township 17S	Range 37E
Date Work Performed 4-25-64	Pool Midway Abo		County Lea		
THIS IS A REPORT OF: (Check appropriate block)					
<input type="checkbox"/> Beginning Drilling Operations		<input type="checkbox"/> Casing Test and Cement Job		<input checked="" type="checkbox"/> Other (Explain):	
<input type="checkbox"/> Plugging		<input type="checkbox"/> Remedial Work			

Detailed account of work done, nature and quantity of materials used, and results obtained.

Repair Leak at Liner Top: Well had been flowing through 2-7/8" tubing with packer set at 8794'. Well ceased to flow. Pulled packer and put well on pump. Produced 100% water. Pulled rods and tubing. Located leak at liner top 3871'. Cement top of liner with 175 sx. Dowell CL-C cement. Pressure test to 1000 psig. Put well back on pump.

Witnessed by W. H. Williams		Position Chief Engineer		Company Consolidated Oil & Gas, Inc.		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P B T D	Producing Interval		Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by				Name		
Title				Position		
Date				Company		
				Consolidated Oil & Gas, Inc.		