

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

COPY TO U. S. G. S.  
SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

00-5119 LC 0592-5

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

7. UNIT AGREEMENT NAME  
TR 16

2. NAME OF OPERATOR  
C.E. LaRue & B.N. Muncy, Jr.

8. FARM OR LEASE NAME  
Pearsall Queen Sand Unit

3. ADDRESS OF OPERATOR  
P. O. Box 196 Aretsia, New Mexico 88210

9. WELL NO.  
1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

10. FIELD AND POOL, OR WILDCAT

Pearsall Queen

2310 FSL & 1650 FWL; Section 4, T 18S, R 32E

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Section 4, T 18S, R 32E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3852 GL

12. COUNTY OR PARISH 18. STATE  
Lea N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) plumbing for casing leak survey

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Installed necessary plumbing for casing leak survey.

Two inch was plumbed to surface with a braiding head connection consistion of a 2000# valve. At or above the surface, a one inch swag3 was connected to a one inch 2000# valve.

Inspected and approved by Ms. W. Kelly, March 22, 1979.

RECEIVED

APR 24 1979

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE

Overseer

ACCEPTED FOR RECORD

DATE

(This space for Federal or State office use)

APR 24 1979

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

DEPARTMENT OF SURVEY  
GENERAL LAND OFFICE  
MEXICO

RECEIVED  
MAY 1970  
OFFICE