Submit 3 Copies To Appropriate District	State of N	rico		Form	C-103			
Office	Energy, Minerals and Natural Resources			Revised March 25, 1999				
District I				WELL API	NO.			
1625 N. French Dr., Hobbs, NM 87240				30 - 025 - 20675				
District II 811 South First, Artesia, NM 87210	OIL CONSERVA	OIL CONSERVATION DIVISION			Type of I			
District III	rict III 2040 South Pacheco 0 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 rict IV			STA'		FEE		
1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas Lease No.				
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505				B - 2287				
				7 1				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:					
(DO NOT USE THIS FORM FOR PROPOSA	Name.			1				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Sur Stata					
PROPOSALS.) 1. Type of Well:				Sun State				
Oil Well Gas Well	Other							
2. Name of Operator				8. Well N	0.			
Nadel and Gussman Permian, L.L.C.					1			
3. Address of Operator			9. Pool name or Wildcat					
601 N Marienfeld, Suite 508, Midland, Texas 79701			Vacuum	Grayb	urg San An	dres		
	eld, Suite Ecoy IIII							
4. Well Location						North	line	
Unit Letter: <u>E</u> ::	660' feet from the	West	line and 1	<u>980'</u> fee	t from th	e <u>North</u>	IIIIe	
Section 19	Township 17 S	Ra	nge 36 E	NM	PM	Lea Co	ounty	
	1. Elevation (Show w	hether DF	P, RKB, RT, GR, etc	c.)			e e e	
		3895'	GL					
11. Check At	ppropriate Box to Ind	licate Na	ture of Notice,	Report or C	)ther Da	ata		
NOTICE OF IN	TENTION TO:		SOR	SEQUEN		URIUF.		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	K		ALTERING CA		
					. —			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS		PLUG AND ABANDONME		
		<b>F</b> -7	CASING TEST A	ND				
PULL OR ALTER CASING			CEMENT JOB					
	COMPLETION		OTHER:					
OTHER:								

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

## 6-22-00:

- 1. Rigged up vacuum truck. Bled off intermediate and production casing.
- 2. Set CIBP at 4615' and dumped 4 sx on top by bailer.
- 3. Tested casing to 670 psi for 35 minutes OK. Chart on back.

## 7-7-00:

50

- 4. Ran annual bradenhead survey: test failed because of water and oil flow on intermediate casing.
- 5. We will submit a separate procedure to plug and abandon the well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.									
SIGNATURE_	TITLE	<b>Operations</b> Engineer		DATE	7-12-00				
Type or print name Robert McNaughton		Telephone No.	.915 -	- 682 - 4429	)				
(This space for State use)	· · ·			.*	e 1				
APPPROVED BY	TITLE			DATE					





