NO. OF COPIES RECEIVED	
DISTRIBUTION	Form C-103 Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State Fee X
OPERATOR	5. State Oil & Gas Lease No.
	1
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL X GAS WELL OTHER-  2. Name of Operator	7. Unit Agreement Name
Exxon Company, U.S.A.	8. Farm or Lease Name
3. Address of Operator	Charles S. Alves
1700 West Broadway, Andrews, Texas 79714	9. Well No.
4. Location of Well	#2
C 520 M 0100	10. Field and Pool, or Wildcat
UNIT LETTER C . 520 FEET FROM THE NL LINE AND 2120 FEET FROM	Scharb-Bone Springs
THE WL LINE, SECTION 7 TOWNSHIP 19-S RANGE 25-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3905 D.F.	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  Change PLANS  Change PLANS  CASING TEST AND CEMENT JOB	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposes
PUMP INTO 27/8 CSC TO ESTABLISH INJ. RATE. IF SUFFICIENT RATE  275 SXS CAT. DOWN 27/8" CSG. LEAVING CEMENT AT SURFACE. IF S  OBTAINED, RUN 11/2" TBC TD 7500'. CIRC. HOLE W/9.5#/CAL. MUD  CEMENT PLUCS THRU TBC. AS FOLLOWS:  A. 100' PLUC FROM THOO-7500 W/3 SXS.  B. 100' PLUC ACROSS THE INFERMEDIATE CSC. SHOE FROM 3950-40.  C. 100' PLUC BELOW THE BASE OF THE SANTA ROSA FROM 1750-11.  D. 100' PLUC ACROSS THE SURFACE CSG. SHOE FROM 367-467' &  E. 10' PLUC AT THE SURFACE.	SUFFICIENT RATE NOT  LADEL BRINE. SPOT  50' 4/3 5KS.  850' 4/3 5KS.  1/3 5KS.
PUMP ALL PLUCS DOWN W/9.5#/CAL. MUD LADER BRINE. TAC STRING TO VERIFY PLACEMENT.	
LATCH OND 85/8"- 13 3/8" ANNULUS AND ATTEMPT TO FSTAB	LISH AN INSECTION

RATE. EF SUFFICIENT RATE OBTAINED BULLHEAD 200 SXS CONT DOWN ANDULUS LEAVING CENT. AT SURFACE. IF UNABLE TO ATTAIN RATE, RUN 11/2" TBG DOWN 85/5" 137/8" ANULUS, AS DEEP AS POSSIBLE AND SPOT CEMENT TO THE SURFACE. RIC WELLHEAD FOR ABANDONMENT AND INSTALL MARKER

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNED	my det	TITLE UNIT HEAD	DATE 10-16-74	
APPROVED BY	Orle Signed by	TITLE	DATE	
CONDITIONS OF APPROV	T)-		DATE	