

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RE - ENTRY

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-498
7. Unit Agreement Name
8. Farm or Lease Name C.W. Trainer "25" State
9. Well No. One
10. Field and Pool, or Wildcat Wildcat
12. County LEA

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXAS CRUDE, INC.,
3. Address of Operator 508 Wall Towers East, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17 S</u> RANGE <u>36 E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3805.55' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Re-Entry of Permzoil United - State</u> <input type="checkbox"/> <u>25 Well #1 (drilled in 1964, P&A 3-23-72)</u>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
12-1-72 - The following procedure was approved by OCC Office in Hobbs, N.M., before work was done: Cleaned out to 7226' - Straddle Tested from 6845-7010 and 6645-6845. No Oil or Gas recovered. Spotted the following cement plugs: 40 sacks from 6600-6455; 40 sacks from 5600-5465; 40 sacks in bottom of 8 5/8" 4790-4655. Pulled 8 5/8" casing from approximately 1020', set 50 sacks from 1050-950'; 50 sacks in bottom of 13 3/8" from 340-240; 10 sack plug in top of 13 3/8" casing. Welded plat in top of 13 3/8" casing. Erected dry hole marker. Work completed 12-1-72

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. D. Lettleson TITLE Dist. Supt DATE 12-1-72
APPROVED BY Arthur C. Clegg TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

1942

OIL CONSERVATION BOARD
HONOLULU, H. I.