

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
(MADE AVAILABLE FOR REGULAR USE BY FORM C-1011 FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Operator
Shell Oil Company

Address
P. O. Box 1509, Midland, TX 79702

Well Name

UNIT LETTER G 2180 FEET FROM THE N LINE AND 1980 FEET FROM

East LINE, SECTION 28 TOWNSHIP 17S RANGE 35E

15. Elevation (Show whether DF, RF, GR, etc.)
3953' DF

7. Unit Agreement Name
8. Form or Lease Name
State N
9. Well No.
4
10. Field and Pool, or Wildcat
Vacuum (Glorieta)
11. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
REPAIR OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

2. Description of Work to be Completed: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.)

PLUG BACK TO SHUT OFF WATER ENTRY

- 5-22-78: Pulled equip. Ran and set RBP @ 6153' on 2-3/8" tbg.
- 5-23-78: Ran 20-150-RHBC-20-0 pump. Started well ppg.
- 5-24-78: thru
- 5-31-78: Testing upper perf's.
- 6-01-78: Moved RBP to 6125'. Reran pmp and hung well on.
- 6-02-78: thru
- 6-07-78: Testing upper perf's.
- 6-08-78: Hung 2-3/8" tbg @ 6166'.

(OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

J. E. Sullivan

SIGNED *J. E. Sullivan*

TITLE Senior Engineering Technician DATE 11-01-78

APPROVED BY
CONDITIONS OF APPROVAL, *Dist. 1, Supr.*

TITLE

NOV 6 1978

(CONTINUED FROM FRONT)

6-09-78: Reran equip. Started well ppg from all perf's.

6-10-78:
thru

6-13-78: Testing.

6-14-78: On 24 hr test ppg 21 BO and 149 BW - operation to shut off water entry unsuccessful.

6-18-78
IN COMM
6-18-78