## HUMBER OF COP LE RECEIVED DISTRIBUTION BANTA FE FILE U.S. G.S. LAND OFFICE TRANSPORTER GAS PRORATION OFFICE OPERATOR

## NEVY MEXICO OIL CONSERVATION COMMISSION Santa Fe. New Mexico

(Form C-104) Revised 7/1/57

## REQUEST FOR (OIL) - (GAS) ALLOWAPLE

Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Caremast bear proported on 165,1025 psia at 60° Fahrenheit.

	ile mereli lad	into	Atlantic Richfield tive Merch in ell	Company	Hobb	s, New Mex	Lee	Septe	mber 17,	196
WE ARE I	LEKEBY 1	REOPEST	ingparatio	DAVŽABLE FO	Plac Or A. WEI	:e) .t. Known	AS.		(Date)	
Sinela	ir Oil &	Gas Com	p <b>any</b>	State B 1	576 W.	II No. 8	in	SW ,	. SW	1/
( ( )	mpany or O	perator)		(Lease	: 1					
um L	Se	c32	, T. 178	, R <b>35</b> #	, NMP	M.,	acum (il	ori eta	****************	.Pool
•		Lea	County De	sea Spuddad	8-29-6	a Date	Delline Co	enleted	9-13-6/	L
	se indicate					Total Depth_				
		<del></del>				Name of Prod.				
D	C B	A	PRODUCING IN			<del></del>			<del></del> ,	
					6069-781	and 6086-9	) <u>L</u> 1			
E	F G	H	I .	The state of the s	NAME COMMENTS AND PROPERTY OF THE PERSON.	Depth Casing Shoe		Depth	60891	
			1		<del>`</del>	casing Shoe	02.00	lubing_	0004.	
L	K J	I	OIL WELL TES	Majorn .					CI	hoke
						,bb				_
M	N O	P	Test After A	cid or Fractu	re Treatment	(after recove	ry of volume	of oil equ	al to volume	e of
x	.   .		load oil use	ed): <b>43</b>	bbls.oil,	O bbls w	ater in <u>9</u>	_hrs, <u>0</u>	_min. Size_	17/6
//247			GAS WELL TES	<u> </u>						
660'Fr S	FOOTAGE)	Fr W Lin	OS Natural Prod	l. Test:		_MCF/Day; Hour	s flowed	Choke	Size	
tubing ,Cas	ing and Com	enting Reco	_			re, etc.):				
Size	Feet	Sax				:				
8-5/8H	15501	700	Ĭ.							
<u> </u>		100								
4-1/2"	62001	1332	Acid or Fractions 500	ture Treatment	t (Give amou	nts of material	s used, such	as acid, v	water, oil,	and
2-3/8	60801	Tubing	***************************************			first new			_	
	-	- 4-5-1-6				first new run to tanks		•		
						es Pipe Li	-	•		
ļ	L	<del></del>				Louis Compan				
Remarks:			*****************				****			
			***************************************			****	*************	••		
		******************					******	• • • • • • • • • • • • • • • • • • • •	••••••	
	-		ormation given							
Approved			************	, 19	***************************************	Sincleir	mpany or Op		<b>V</b>	
٥.		D \$ 1 4 PP 2 O S S		<b></b> ,	, L	-1 /	2-7-7-27			
. ŅI	L CONSE	KVATION	COMMISSIO	JN -	by	Marit	(Signature)			
					Title	District				
,	,				Name	Send Commu	nications re	garding we	ell to:	
			S, cofile		rame	Bex 1920,	Hebba.	iew Xerd	00. 882	.0