

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Consolidated Oil & Gas, Inc.		Address 4150 E. Mexico Ave., Denver 22, Colorado			
Lease Midway State	Well No. 2-8	Unit Letter O	Section 8	Township 17S	Range 37E
Date Work Performed 12/25/64	Pool Midway Abo		County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran 142 joints of 24 and 32 lb. 8-5/8" intermediate casing equipped with guide shoe and differential fill-up collar and set at 4354' KB. Cemented with 200 sacks of Dowell 50/50 Pozmix followed with 150 sacks of regular cement with 2 lb. salt per sack. Used two-plug displacement method with water. WOC 24 hrs. Pressure tested casing and cement job to 1000 psig. Held okay.

Witnessed by Tom Richey	Position Tool Pusher	Company Hondo Drilling Company
----------------------------	-------------------------	-----------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name <i>Wayne Rogers</i>
Title	Position Production Manager
Date	Company Consolidated Oil & Gas, Inc.