Form 3160-5 (June 1990)

UNITED STATES

FORM APPROVED

(Julie 1770)	DEPARTME BUREAU OF	NT OF THE INTERIOR LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires: March 31, 1993
			5. Lease Designation and Serial No.
Do not use	this form for proposals to c	S AND REPORTS ON WELLS Irill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	NM -05519 -0445 6. If Indian, Allottee or Tribe Name
	TOO THE PORTION TO	Tor such proposals	
1. Type of Well	SUBMI	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation Mescalero Ridge Unit
			891007465B
2. Name of Opera			8. Well Name and No.
Hondo Oil & Gas Company			Mescalero Ridge Unit #
3. Address and Telephone No.			9. API Well No.
P O Por 2000 P			3002522081 00 \$1
4 Location of Well (Footage, Sec., T., R., M., or Survey D		1, NM 88202 (505)625-6732	10. Field and Pool, or Exploratory Area
			Pearl Queen
1650' FSL & 1980' FWL; Sec.26-T19S-R34E			11. County or Parish, State
		- 1230 K34L	Lea Co., NM
12 CH	ECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	T. OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
Notice of Intent			
		Abandonment	Change of Plans
Subsequent Report Final Abandonment Notice		Recompletion	New Construction
		Plugging Back Casing Repair	☐ Non-Routine Fracturing
		Altering Casing	Water Shut-Off
		Other Repair hole in thg.	Conversion to Injection
			Dispose Water (Note: Report results of multiple completion on Well
3. Describe Propose	ed or Completed Operations (Clearly state al	l pertinent details, and give pertinent dates, including estimated date of starting at all depths for all markers and zones pertinent to this work.	Completion or Recompletion Report and Log form)
give subsuri	face locations and measured and true vertice	a depths for all markers and zones pertinent to this work.)*	ny proposed work. If well is directionally drilled,
6/1	pkr, pick up 5 TIH testing 500 149 jts 4594.45 Set pkr @ 4610.	unit, unflange, pick up on tubing, tub k up 6 jts 2 3/8" tbg, screwed into fis ½" X 2 3/8" Locset with 1.50 profile a 90 above slips, found 2 bad jts, replac 62 7/8" IPC EUE & pkr = 5.20 KBS 11' T 65' displaced annulus w/ pkr fluid 2% is anged up test well to 500 psi for 30 m on @ 5:00 p.m.	h, TOH w/ tbg & nd on/off tool, ed l collar, ran otal 4610.65'.
	-	Ade	
		·	

14. I hereby certify that the foregoing is true and correct Title Petroleum Engineer 06/24/91 Approved by _______ Conditions of approval, if any: Title _

Date_

SENT BY:HONDO LOVINGTON 26-18-31 06:49AM პ. პ650→ 5056256758 # 1 - MIBHT H u YAO as

396665∅→

5056256758;# 1

RCV EN: XEROX TELECOPIER 7011 ; 6-18-91 6:48AM ;