NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE			Form C-103 Supersedes Old C-102 and C-103
FILE		ALCO OLE CONSERVATION COMMISSION	Effective 1-1-65
		007 11 1. 10 11 1. 17	C - Indiana II
U.S.G.S.		(0,0) = (1,0) = (1,0) = (1,0)	5a. Indicate Type of Lease State X Fee
LAND OFFICE			
OPERATOR			5. State Oil & Gas Lease No. B-1040
(DO NOT USE THIS FORM USE **/			
I. OIL GAS WELL WELL	Dril	lling	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name		
Amerada	State V "A"		
3. Address of Operator		<u>_</u>	9. Well No.
P. O. Bo	6		
4. Location of Well			10. Field and Pool, or Wildcat
<u>v</u>	660	South 660	Vacuum
UNIT LETTER	. FEET FROM		TACUUH
		THE LINE AND FI	
	E, SECTION TO		
	E, SECTION TO	DWNSHIP 17-S RANGE 34-E	NMPM.
THE West	e, section to	IT-S RANGE 34-E	NMPM. 12. County Lea
тне West LIN	e, section to	17-S 34-E Non (Show whether DF, RT, GR, etc.) To Indicate Nature of Notice, Report	NMPM. 12. County Lea
тне West LIN	23 To 15, Elevati Check Appropriate Box OF INTENTION TO:	17-S 34-E Non (Show whether DF, RT, GR, etc.) To Indicate Nature of Notice, Report	I or Other Data
	23 To 15, Elevati Check Appropriate Box OF INTENTION TO:	17-S RANGE 34-E Ion (Show whether DF, RT, GR, etc.) To Indicate Nature of Notice, Report SUBSE	I OF OTHER DATA QUENT REPORT OF:
THE West LIN	23 To To To To To To To To To To	17-S 34-E Ion (Show whether DF, RT, GR, etc.) To Indicate Nature of Notice, Report SUBSE AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	Lea Or Other Data QUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
THE LIN	23 To To To To To To To To To To	17-S 34-E Ion (Show whether DF, RT, GR, etc.) To Indicate Nature of Notice, Report SUBSE AND ABANDON Remedial work commence drilling opns.	Lea Or Other Data QUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
THE LIN	23 To To To To To To To To To To	17-S 34-E NON (Show whether DF, RT, GR, etc.) 34-E To Indicate Nature of Notice, Report SUBSE AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB	Lea or Other Data QUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT

Spudded 12-1/4" hole at 7:30 PM 10-6-67. Reduced hole from 12-1/4" to 11" at 1583' and drilled 11" hole to 1596'. Ran 50 jts. 8-5/8" OD casing set at 1594' and cemented with 975 sx. Trinity Lite-Wate and 100 sx. Class "H" cement with 2% Calcium Chloride. Total 1075 sx. Pumped plug to 1526' at 11:30 AM 10-10-67 with 1500# PP. Cement circulated. Waited 22-1/2 hrs. Tested 8-5/8" casing with 1300#. Held OK. Started drilling 7-7/8" hole at 1596'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

stille hel SIGNE

SIGNED ROUCED	TITLE District Superintendent	lent 10-12-67
APPROVED BY John W. Rumpan CONDITIONS OF APPROVAL, IF ANY:	тітце	DATE