NO. OF COPIES RECEIVED			Form C-103	
DISTRIBUTION			Supersedes Old	
SANTA FE		SERVATION COMMISSION	C-102 and C-103	
FILE		SERVATION COMMISSION	Effective 1-1-65	
U.S.G.S.	\uparrow \uparrow	· · · · · · · · · · · · · · · · · · ·	5a. Indicate Type of Lease	
LAND OFFICE		2 <u>20</u> 11 200		
OPERATOR	_			
OFERATOR			5. State Oil & Gas Lease No.	
			<u>B - 1196</u>	
(DO NOT USE THIS FORM FOR PR USE "APPLICA"	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG E	WELLS BACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)		
CIL GAS WELL X WELL	OTHER.		7. Unit Agreement Name	
2. Name of Operator			8. Farm or Lease Name	
Deser				
Pennzoil United, Inc.			Mobil "24" State Comm	
			9, well No.	
P. O. Drawer 1828 - Midland, Texas 79701			1	
			10. Field and Pool, or Wildcat	
UNIT LETTERH 2121 FEET FROM THE North Line and 801 FEET FROM			N. Vacuum (Abo)	
THE East LINE, SECTI	ION TOWNSHIP	BANCE 34-E		
			·/////////////////////////////////////	
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	
AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII				
^{16.} Check				
	Appropriate Box To Indicate N	lature of Notice, Report or Ot	her Data	
NOTICE OF INTENTION TO: SUBSEQUENT			T REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		OTHER		
OTHER				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 9-19-68 Spudded 17%" hole at 2:30 P.M. Drilled to 357' Ran 11 jts. 13 3/8" OD, 48# casing to 352' Cement w/140 sx Class "A" 6% gel plus 150 sx Class "A" 2% CaCl. Plug down at 2:20 A.M. 9-20-68. Cement circulated O.K. After 18 hrs, tested casing w/1000# for 30 minutes 0.K.
- 9-26-68 Drilled 11" hole to 4,000' Ran 8 5/8" OD, 24# & 32# casing to 4000'. -Cement w/570 sx Class "H" 50/50 posmix 6% gel w/22# salt per sack plus 150 sx Class "H" w/8# salt per sack. Plug down at 3:30 P.M.
- 9-27-68 Ran temperature survey. Top cement 2430'. After 24 hrs, tested casing w/ 1500# for 30 minutes. O.K.

18. I hereby certify that the information above is true and comp.	ete to the best of my knowledge and belief.		
signed Andreck	Drilling Superintendent	DATE	10-4-68
APPROVED BY Jeslig No Clements	TITLE		17. 17.65
CONDITIONS OF APPROVAL, IF ANY:		DATE	