

- 11476-77            Ls mgry, fn xln, dnse no vis Ø, some spotty weak fluor on poss frac places - tight.
- 11477-78            Ls, mgry, fn xln, dnse, no vis Ø, some spotty fluor on poss frac face - tight.
- 11478-79            Ls, AA, no vis Ø, some spotty fluor on poss frac planes dnse, tight.

GENERAL VISIBLE CHARACTERISTICS

- From 11440-52            Sli bldg oil and salt water from vertical fracture at 442. Vuggs and pp Ø have some visible stain, gives spotty to streaked stained appearance.
- 11452-53            Vuggs & pp, sli bldg oil & SW, occasional hairline vert frac, spotty stain.
- 11453-56            Sli bldg O and SW, pp and small vuggs, some vertical hariline fracs- spotty stain.
- 11456-62            Few scatt pp and vuggs, styolite at 455 and 61, sli bldg SW w/ sli oil stain.
- 11462-69            Few scatt pp and vuggs, uneven to mottled, spotty stain, sli bldg SW and Oil.
- 11469-80            Few scatt isolated pp and small vuggs, mottled appearing, last three feet very tight, sli bldy SW and Oil, vert frac 11464-68, 11472-73, 11474-76