

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. State Oil & Gas Lease No. L-5391</p>
<p>2. Name of Operator Mobil Oil Corporation</p>		<p>7. Unit Agreement Name State UU Com</p>
<p>3. Address of Operator Box 633, Midland, Texas 79701</p>		<p>8. Farm or Lease Name</p>
<p>4. Location of Well UNIT LETTER F, 1907 FEET FROM THE West LINE AND 1980 FEET FROM THE North LINE, SECTION 7 TOWNSHIP 17-S RANGE 35-E NMPM.</p>		<p>9. Well No. 1</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4009.5</p>		<p>10. Field and Pool, or Wildcat Undesignated</p>
<p>12. County Lea</p>		

<p align="center">Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-30-74 Ran 121 Jts 5000' 9-5/8 OD 43.50# S95 8rd LT&C
csg. Howco cmt'd csg on bottom w/3500x Class C cmt w/6%
gel + 1/4# flocele in 1st 1000x + 200x Class C Neat cmt,
Cmt circ, WOC 44 hrs. test csg 3000#/15 mins OK

Casing pattern was changed on this well (9-5/8 rather than 8-5/8)
because of pipe shortage.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine D. Tucker TITLE Proration Clerk DATE 5-1-74

APPROVED BY Joe D. Ramsey TITLE Dist. I, Supv. DATE 5-1-74

CONDITIONS OF APPROVAL, IF ANY: