F	GY AND MINERALS DEPARTM	OIL CONSERVATION DIVISION	Form C-103
-	DISTRIBUTION	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Revised 10-1-78
	TILE		
1	J.S.G.S.		Sa. Inaicate Type of Lease
	AND OFFICE		State X Fee
	PERATOR		5. State Oli & Gas Lease No.
			0G - 454
	SUND		
· · · · · · · · · · · · · · · · · · ·			7. Unit Agreement Name
011 W E		OTHER.	
2. Name of Operator			8. Form or Lease Name
Southern Union Exploration Company			Supco State
13. Address of Operator			9. Well No.
1217 Main Street, Suite 400 Dallas, Texas 75202			2
4. Location of Well			10. Field and Pool, or Wildcat
UNIT-LETTER G, 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM			N Treese Atesta M
	IT-LETTERG	1900 FEET FROM THE NOT LIL LINE AND 1980 FEET	MON
	Fact	17 170 0/7	///////////////////////////////
TH	LASL LINE, SECT	10N 17 TOWNSHIP 17S RANGE 34E N	MBM: (()))))))))))))))))))))))))))))))))))
1111		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
7117.		4086' GL	Lea
16.	Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		-	ENT REPORT OF:
PERFOR	M REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			
-	'	OT HER	
OTH			
	····		

- 1. Drilled out remainder of cement from casing leak squeeze.
 - 2. RIH and set a CIBP at 9090' and dumped 2 sacks of cement on top.
 - 3. Pressure tested the squeeze job to 500 psi held ok.
 - 4. Perforated the Abo from 8858'-8870', 8872'-8878', 8881'-8898', 8912'-8917', 8919'-8930', and 8936'-8946' (1 SPF).
 - 5. Acidized with 11,000 gals 15% NEFE acid.
 - 6. Swabbed back acid and set well up to pump.

Worked was performed from 2-26-85 to 3-15-85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Drilling & Production Engineer DATE March 22, 1985

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

NAR 25 1985